


EVOLUTION E2 BENCH PARTS

You should have:



| ITEM | Quantity x Size in Cm | | | | |
|------------------------------------|-----------------------|----------------|----------------|----------------|----------------|
| | 60950 EB160 | 60951 EB210 | 60952 EB260 | 60953 EB310 | 60954 EB360 |
| Beam A (Front to back) PJ32/001 | 4x125 | 6x125 | 6x125 | 6x125 | 6x125 |
| Beam B (Side to side) PJ**/001 | 3x182 PJ28 | 6x114 PJ05 | 6x139 PJ29 | 6x164 PJ30 | 6x189 PJ31 |
| Leg PH06/001 | 4 x 87 | 6 x 87 | 6 x 87 | 6 x 87 | 6 x 87 |
| Bench Edge Extrusion KB**/100 | 1x182 KB22 | 2x114 KB23 | 2x139 KB24 | 2x164 KB25 | 2x189 KB26 |
| LH Bracket CA10/427 | 1 | 1 | 1 | 1 | 1 |
| Centre Bracket CA10/428 | 0 | 1 | 1 | 1 | 1 |
| RH Bracket CA10/426 | 1 | 1 | 1 | 1 | 1 |
| Fixing Block KB22/101 | 2 | 2 | 2 | 2 | 2 |
| End Fixing Screws CA30/323 | 4 | 4 | 4 | 4 | 4 |
| Base Bracket Screws CA30/016 | 8 | 10 | 12 | 14 | 16 |
| Joining Bracket PK01/001 | 16 | 28 | 28 | 28 | 28 |
| Grub Screw CA30/199 | 48 | 84 | 84 | 84 | 84 |
| Worktop Fixing PC11/100 | 6 | 11 | 11 | 11 | 11 |
| Long Screw CA30/255 | 6 | 11 | 11 | 11 | 11 |
| Height Adjuster PP01/000 | 4 | 6 | 6 | 16 | 6 |
| 4mm Hexagon Wrench CA25/114 | 1 | 1 | 1 | 1 | 1 |
| Spacer PJ99/001 | 1 | 1 | 1 | 1 | 1 |
| 4mm Hexagon Driver Bit CA25/320 | 1 | 1 | 1 | 1 | 1 |