


Professional M Series - Cutting Head Parts Diagram (inc parts sub-assemblies)

Notes: Parts are sold individually unless specified as a set.



Notes: -
M105 is not required for M12, M15 or M18.

