


Professional M Series - Parts Diagram



Notes: -
 Parts marked with a (XX) are size dependent. Replace the XX with specific Machine Size (e.g. MT(XX) for M36 = MT36).
 Parts marked with an (X) vary in quantity dependent on the Machine Size (e.g. M107 for M12 - 4 feet, for M54 - 8 feet)
 M105 is not required for M12, M15 or M18.
 Parts are sold individually unless specified as a set.

CSKIT Assembly

U2 (2)
 M133
 M109 (2)